

# Oil Field Environmental Incident Summary

**Incident:** 20160617220738      **Date/Time of Notice:** 06/17/2016 22:07

**Responsible Party:** LIME ROCK RESOURCES III-A, L.P.

**Well Operator:** LIME ROCK RESOURCES III-A, L.P.

**Well Name:** STATE BRIAN SADOWSKY 1-10-3H-142-97

**Field Name:** WILLMEN

**Well File #:** 20572

**Date Incident:** 6/17/2016

**Time Incident:** 15:37

**Facility ID Number:**

**County:** DUNN

**Twp:** 142

**Rng:** 97

**Sec:** 10

**Qtr:**

## Location Description:

**Submitted By:** Robyn Espinoza

**Received By:**

**Contact Person:** Robyn Espinoza  
1111 BAGBY, SUITE 4600  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2.5	Barrels	2	Barrels	2	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/19/2016

**Clean Up Concluded:** 6/23/2016

**Risk Evaluation:**

Contaminated surface material

**Areal Extent:**

**Potential Environmental Impacts:**

Contaminated surface material

**Action Taken or Planned:**

A vac truck was immediately dispatched to recover all standing fluids, all contaminated surface materials will be removed of and disposed of

**Wastes Disposal Location:** Chimney Butte

**Agencies Involved:**

**Updates**

---

**Date:** 6/20/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release remained on location. NDIC has oversight.