

Oil Field Environmental Incident Summary

Incident: 20160618100219 **Date/Time of Notice:** 06/18/2016 10:02

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL 34-0509H

Field Name: PARSHALL

Well File #: 25254

Date Incident: 6/17/2016 **Time Incident:** 13:30

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 5

Qtr: NE NE

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	7	Barrels	7	Barrels	7	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/31/2016

Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Liquids were removed with vac truck and the rock inside lined containment will be washed/flushed with fresh water and removed with vac truck and the repairs have been made.

Wastes Disposal Location: EOG SWD

Agencies Involved:

Updates

Date: 6/20/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC has oversight.