

Oil Field Environmental Incident Summary

Incident: 20160620103731 **Date/Time of Notice:** 06/20/2016 10:37

Responsible Party: MARATHON OIL COMPANY

Well Operator: MARATHON OIL COMPANY

Well Name: APPELDOORN SWD 1

Field Name: BAILEY

Well File #: 90126

Date Incident: 6/19/2016 **Time Incident:** 08:00

Facility ID Number:

County: DUNN

Twp: 145 **Rng:** 93 **Sec:** 19 **Qtr:**

Location Description: Spill was contained within the lined metal containment around the facility.

Submitted By: Duell Petsch

Received By:

Contact Person: Duell Petsch
3172 HWY 22 N
DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	20	Barrels	20	Barrels	20	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/30/2016

Clean Up Concluded: 6/19/2016

Risk Evaluation:

No immediate risk as spill was entirely contained and cleanup has been completed.

Areal Extent:

Potential Environmental Impacts:

Minimal environmental impacts as spill was entirely contained within the lined metal containment. Cleanup has been completed for the spill.

Action Taken or Planned:

Investigation is ongoing to determine the cause of the weld breaking. Once the cause is determined corrective action will be taken to minimize the chance of this event re-occurring.

Wastes Disposal Location: Recovered waste was disposed of at the Appledoorn Saltwater Disposal facility.

Agencies Involved:

Updates

Date: 6/20/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The spill was contained within dike. NDIC has oversight.