

Oil Field Environmental Incident Summary

Incident: 20160622083905 **Date/Time of Notice:** 06/22/2016 08:39
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: COPPER DRAW 24-22TFH 2SH
Field Name: JOHNSON CORNER **Well File #:** 23646
Date Incident: 6/21/2016 **Time Incident:** 19:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 150 **Rng:** 96 **Sec:** 22 **Qtr:** SW SE
Location Description: Packing leak that resulted in a spill of 28 bbls of production water with a skim of oil. All fluids stayed on location

Submitted By: Joselynn Adams **Received By:**

Contact Person: Joselynn Adams
600 N. DAIRY ASHFORD
HOUSTON, TX 77079

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 800 Feet
Distance Nearest Water Well: 800 Feet

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Facility Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	28	Barrels	28	Barrels		
Other						

Description of Other Released Contaminant:

There was a small skim of oil on the produced water

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

Spill was contained. Minimal risk. A vac truck will be used to collect contaminated soil

Areal Extent:

Potential Environmental Impacts:

Spill to the ground.

Action Taken or Planned:

Work order generated to clean up spill

Wastes Disposal Location: Closest waste disposal site.

Agencies Involved:

Updates

Date: 6/22/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to packing leak, remained on location according to the report. NDIC retains oversight.