

# Oil Field Environmental Incident Summary

**Incident:** 20160702120220      **Date/Time of Notice:** 07/02/2016 12:02

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** DANIEL 3-33H1

**Field Name:** STONEVIEW

**Well File #:** 27871

**Date Incident:** 7/1/2016      **Time Incident:** 16:30

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 160

**Rng:** 95

**Sec:** 28

**Qtr:**

**Location Description:**

**Submitted By:** Timothy Ilse

**Received By:**

**Contact Person:** Lane Titus  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.1	Barrels	0.1	Barrels	0.1	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 12/15/2016

**Clean Up Concluded:** 7/2/2016

**Risk Evaluation:**

None

**Areal Extent:**

About 60 ft. by 100 ft. area offsite

**Potential Environmental Impacts:**

Vegetation and topsoil

**Action Taken or Planned:**

All visibly contaminated material was removed and disposed of at R360 Disposal

**Wastes Disposal Location:** R360 Disposal

**Agencies Involved:** Scott Deilie @ 11:59 on 7/2/2016

**Updates**

---

**Date:** 7/5/2016    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted areas off location. Follow-up is required.

---

**Date:** 7/11/2016    **Status:** Inspection

**Author:** Schiermeister, Robin

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site 7-6-16 at 2:22 p.m. It was sunny and approximately 75 degrees. An area in the field to the north of the pad had been mowed. This area extended 250 feet east to west and 50 feet up a 30-degree slope to the north. A check for vegetation is needed at a later date.