

Oil Field Environmental Incident Summary

Incident: 20160713103534 **Date/Time of Notice:** 07/13/2016 10:35

Responsible Party: LIME ROCK RESOURCES III-A, L.P.

Well Operator: LIME ROCK RESOURCES III-A, L.P.

Well Name: VELENCHENKO 2-4-9H-143-97

Field Name: CROOKED CREEK

Well File #: 27286

Date Incident: 7/12/2016 **Time Incident:** 10:00

Facility ID Number:

County: DUNN

Twp: 144 **Rng:** 97 **Sec:** 33 **Qtr:**

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
1111 BAGBY, SUITE 4600
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	1	Barrels	1	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/12/2016

Clean Up Concluded: 7/20/2016

Risk Evaluation:

Contaminated surface material

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material

Action Taken or Planned:

A vac truck was dispatched to recover standing fluids, SM Fencing was immediately dispatched to cut and bagged the affected vegetation and remove all contaminated surface materials

Wastes Disposal Location: Chimney Butte

Agencies Involved:

Updates

Date: 7/13/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained to the well pad. Further follow-up needed.

Date: 7/22/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 7/22/2016 at 9:30 .

No sign of spill at the described location. More follow-up with company needed to ensure proper reporting.