

Oil Field Environmental Incident Summary

Incident: 20160720142057 **Date/Time of Notice:** 07/20/2016 14:20

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: COX 14-12H

Field Name: CEDAR HILLS

Well File #: 14089

Date Incident: 7/19/2016 **Time Incident:** 14:19

Facility ID Number:

County: BOWMAN

Twp: 131

Rng: 105

Sec: 12

Qtr: SW SW

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	5	Barrels		
Brine	10	Barrels	5	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

A vacuum truck was used to pull water off of the tanks and to recover fluids in the dike. Once a determination of cause is established repairs will begin. Contaminated soil will be removed.

Wastes Disposal Location: Liquids to production tank. Solids to PDI Chimney Buttes.

Agencies Involved:

Updates

Date: 7/20/2016 **Status:** Reviewed - Assigned to Other Agency **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.