

Oil Field Environmental Incident Summary

Incident: 20160722171321 **Date/Time of Notice:** 07/22/2016 17:13

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: WOOD 21X-25B

Field Name: TRUAX

Well File #: 20503

Date Incident: 7/22/2016 **Time Incident:** 10:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 25

Qtr:

Location Description:

Submitted By: JORDAN WOLF

Received By:

Contact Person: KAYLAN DIRKX
P.O Box 6506
321 22ND AVE E
WILLISTON, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	50	Barrels			50	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/29/2016

Clean Up Concluded: 8/19/2016

Risk Evaluation:

LELs, health hazard if oil makes skin contact

Areal Extent:

5' x 15' on location outside of the tank containment (north)

Potential Environmental Impacts:

Minimal- only small amount migrated outside the lined metal tank containment, but remained on location.

Action Taken or Planned:

All wells were shut in and the recycle line was isolated. The free oil will be recovered and returned to the production tanks. The impacted material will be removed and hauled to an approved waste disposal facility. More updates will be available throughout the cleanup process.

Wastes Disposal Location: To be determined...

Agencies Involved:

Updates

Date: 7/25/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a piping/valve connection leak, remained on the constructed well site according to the report. NDIC retains oversight.