

# Oil Field Environmental Incident Summary

**Incident:** 20160801123438      **Date/Time of Notice:** 08/01/2016 12:34

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** MARINENKO 145-97-31D-30-1H

**Field Name:** LITTLE KNIFE

**Well File #:** 27595

**Date Incident:** 7/31/2016      **Time Incident:** 10:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 145      **Rng:** 97      **Sec:** 31      **Qtr:**

**Location Description:** Fluid was spilled into county road ditch. 1.75 miles south of Hwy 200 on 122nd Ave SW.

**Submitted By:** Derek Enderud

**Received By:**

**Contact Person:** Derek Enderud  
PO BOX 935  
BISMARCK, ND 58502

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	1	Barrels			1	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 8/4/2016

**Clean Up Concluded:** 8/2/2016

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

Impacted topsoil will be removed, replaced, and reseeded.

**Action Taken or Planned:**

Rig movers and field hands need to double check each load for security.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 8/1/2016    **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release was not contained. Further follow-up is needed.

---

**Date:** 8/22/2016    **Status:** Inspection

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 1430. Location of spill is on the corner at 122nd Ave SW and 6th. The location seems to have some erosion control in place. Electrical conductivity reading came back elevated in some parts of ditch and similar to background in others. Further follow-up is needed to determine progress of Petro-Hunt on cleanup.