

Oil Field Environmental Incident Summary

Incident: 20160805092803 **Date/Time of Notice:** 08/05/2016 09:28

Responsible Party: Crestwood

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 8/4/2016 **Time Incident:** 14:00

Facility ID Number:

County: DUNN

Twp: 148

Rng: 93

Sec: 14

Qtr: SW NW

Location Description: Near the Enerplus Bullhead pad (NWSW Sec. 14 T148N R93W) On pipeline ROW

Submitted By: Joshua Swann

Received By:

Contact Person: Joshua Swann
10702 Hwy 73
Keene, ND 58847

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	100	Barrels	100	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate health hazards

Areal Extent:

Potential Environmental Impacts:

Soil impacted

Action Taken or Planned:

All free product removed. Contaminated soil being excavated. Release was isolated in excavated.

Wastes Disposal Location:

Agencies Involved: NDDOH
MHA Energy
TAT Environmental

Updates

Date: 8/5/2016 **Status:** Reviewed - Assigned to Other Agency **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release of brine was not contained. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.