

# Oil Field Environmental Incident Summary

**Incident:** 20160813124024      **Date/Time of Notice:** 08/13/2016 12:40

**Responsible Party:** LIME ROCK RESOURCES III-A, L.P.

**Well Operator:** LIME ROCK RESOURCES III-A, L.P.

**Well Name:** LOREN HAGEN 1-35-26H-141-97

**Field Name:** ST. ANTHONY

**Well File #:** 23932

**Date Incident:** 8/13/2016      **Time Incident:** 00:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 141

**Rng:** 97

**Sec:** 35

**Qtr:**

## Location Description:

**Submitted By:** Robyn Espinoza

**Received By:**

**Contact Person:** Robyn Espinoza  
1111 BAGBY, SUITE 4600  
HOUSTON, TX 77002

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	25	Barrels			0	barrels

<b>Brine</b>	30	Barrels				
--------------	----	---------	--	--	--	--

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/24/2016

**Clean Up Concluded:** 10/19/2016

**Risk Evaluation:**

Contaminated surface material

**Areal Extent:**

Adjacent crop land North and East of the pad approximate area 300'x80'

**Potential Environmental Impacts:**

Contaminated surface material

**Action Taken or Planned:**

SM Fencing has been dispatched and an emergency one call has been placed so removal of the contaminated materials can begin as soon as possible, the treater shed will be washed and all contaminated vegetation will be cut and bagged. The gasket will be replaced on the treater to help prevent this from happening again. At the completion of the remediation confirmation samples will be taken to ensure adequate remediation.

**Wastes Disposal Location:** Chimney Butte

**Agencies Involved:** NDDoH

**Updates**

---

**Date:** 8/15/2016    **Status:** Correspondence

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received email from company contact and was told a call has been placed to ND One Call. Once the area has been marked, remediation will begin and confirmation samples will be collected. More follow-up required.

---

**Date:** 8/15/2016    **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release impacted areas off location. Follow-up is required.

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived at 1100 MT. To find this well pad, you must go through the Nes Wold well pad up near the butte. A large portion of cropland has been mowed to the north and east side of pad near the treater. Scraping has been done, along with some excavation, within that mowed portion. There is some oil staining left behind. Further follow-up is needed to determine progress of the cleanup. Photos can be found in the report folder.