

# Oil Field Environmental Incident Summary

**Incident:** 20160826125912      **Date/Time of Notice:** 08/26/2016 12:59

**Responsible Party:** MISSOURI BASIN WELL SERVICE, INC.

**Well Operator:** MISSOURI BASIN WELL SERVICE, INC.

**Well Name:** BRENNA SWD 1

**Field Name:** UNION CENTER

**Well File #:** 90217

**Date Incident:** 8/25/2016      **Time Incident:** 13:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 96

**Sec:** 13

**Qtr:**

**Location Description:**

**Submitted By:** Chad Miller

**Received By:**

**Contact Person:** Chad Miller  
PO BOX 458  
BELFIELD, ND 58622

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels				

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None - all contained in dike

**Areal Extent:**

All contained within dike

**Potential Environmental Impacts:**

None - all contained

**Action Taken or Planned:**

All liquids are returned into system. All contaminated solids will be disposed of in a permitted landfill. Repairs to plumbing are being corrected.

**Wastes Disposal Location:** All liquids are returned into system. All contaminated solids will be disposed of in a permitted landfill.

**Agencies Involved:**

**Updates**

---

**Date:** 8/26/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.