

Oil Field Environmental Incident Summary

Incident: 20160923123018 **Date/Time of Notice:** 09/23/2016 12:30

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P VANCE 154-97-14-9-21-15H

Field Name: TRUAX

Well File #: 29092

Date Incident: 9/21/2016

Time Incident: 10:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 97

Sec: 9

Qtr: SW SE

Location Description:

Submitted By: Corissa Zimmer

Received By:

Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1.3 Mile

Distance Nearest Water Well: 1.3 Mile

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Gallons				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/5/2016

Clean Up Concluded: 9/23/2016

Risk Evaluation:

None noted.

Areal Extent:

To the east of location, in the area of the cabins in the field next to it.

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

Whiting will clean the spill from the land to the east and conduct sampling in the area to verify the spill is cleaned.

Wastes Disposal Location: To be determined, possibly Gibson's

Agencies Involved:

Updates

Date: 9/23/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 2 gallons of oil were released and not contained to the site. Further follow-up needed.

Date: 9/29/2016 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 8:15. 50 degrees F, sunny, southeast wind 10-15 mph. Observed the site and took photos. It appeared that the release impacted areas to the east of the well pad. Land use was grazing/pasture land. No petroleum staining of vegetation or soils was noted off the well pad. It appears the impacted vegetation had been cut and removed. No further follow-up needed at this time.