

Oil Field Environmental Incident Summary

Incident: 20161019221456 **Date/Time of Notice:** 10/19/2016 22:14

Responsible Party: Eagle Oilfield Rentals

Well Operator: EOG RESOURCES, INC.

Well Name: SHELL 23-2820H

Field Name: PARSHALL

Well File #: 30781

Date Incident: 10/19/2016 **Time Incident:** 06:40

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 89

Sec: 28

Qtr:

Location Description:

Submitted By: Brenda Vaness

Received By:

Contact Person: Mark Graff
5250 72nd Ave. NW
Palermo, ND 58769

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels			3	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/4/2017

Clean Up Concluded: 10/20/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Eagle Oilfield Rentals made arrangements for standing liquids to be sucked up, and contaminated material to be scraped up and taken to disposal. Once flowback operations have been completed and the open top tank has been removed, further clean-up will be done. EOG Resources will monitor the clean-up activities. Recovered amount is unknown at this time as clean-up has not been fully completed.

Wastes Disposal Location: To be determined

Agencies Involved:

Updates

Date: 10/20/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, was contained on the facility site according to the report. NDIC retains oversight.