

# Oil Field Environmental Incident Summary

**Incident:** 20161027084258      **Date/Time of Notice:** 10/27/2016 08:42

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** SORENSON 11-3H CTB

**Field Name:** SANISH

**Well File #:**

**Date Incident:** 10/26/2016      **Time Incident:** 14:00      **Facility ID Number:** 217912-01

**County:** MOUNTRAIL      **Twp:** 152      **Rng:** 91      **Sec:** 3      **Qtr:** LO T4

**Location Description:** Approximately 0.5 bbls of oil misted directly to the north east off location impacting an area 20' by 20'

**Submitted By:** Brian Wurm

**Received By:**

**Contact Person:** Brian Wurm  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Treater Popoff

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.5	Barrels	0.5	Barrels	0.5	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 11/7/2016

**Clean Up Concluded:** 10/28/2016

**Risk Evaluation:**

None noted, release stopped and clean up in progress

**Areal Extent:**

Approximately 20' by 20' directly north east off location

**Potential Environmental Impacts:**

None noted, release stopped and clean up in progress

**Action Taken or Planned:**

A vac truck was brought in to pick up impacted material on location. Landowner was contacted and requested that impacted vegetation on site be mowed and bagged.

**Wastes Disposal Location:** Secure Disposal facility

**Agencies Involved:**

**Updates**

---

**Date:** 10/27/2016 **Status:** Inspection

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On location 10/27/2016, at 1:45 p.m. Release is to the NE off location. Some light staining is visible on the vegetation. Area was being mowed at time of inspection. Area is approximately 30 X 40 feet. More follow-up is required to check on vegetation growth.

---

**Date:** 10/27/2016 **Status:** Reviewed - Follow-up Required

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to treater popoff, was not contained on location according to the report. Follow-up is necessary.