

General Environmental Incident Summary

Incident: 1265 **Date/Time Notice:** 7/8/2010 1445 **DEM Incident No:**
Responsible Party: CHS
Date Incident: 7/8/2010 **Time Incident:** 1445 **Duration:** 3 minutes
County: Pembina **Twp:** 158 **Rng:** 51 **Sec:** 30 **Qtr:**
Lat: 48.47732 **Long:** -97.26712 **Method:** Derived from TRS
Location Description: 15649 County Rd. 9; Drayton, ND; AH - 10/25/2012 - Could be Section 31.

Submitted By: Gary Berreth **Affiliation:**

Address:

City: **State:** **Zip:**

Received By:

Contact Person: Ben Renberg
5500 Cenex Drive
Invergrove Heights, MN

Distance Nearest Occupied Building: 20 Feet

Type of Incident: Tank Overflow

Description of Released Contaminant: Gasoline/ethanol

Volume Spilled: 50.00 gallons **Ag Related:** Yes

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Routine fuel delivery; tank overfilled and sprayed onto nearby structure.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soil contamination. Siding on structure was sprayed with fuel.

Action Taken or Planned:

Fuel on ground was bermed; WCEC has been contacted to perform followup.

Wastes Disposal Location: Unknown

Agencies Involved:

