

General Environmental Incident Summary

Incident: 1343 **Date/Time Notice:** 1/3/2011 1043 **DEM Incident No:**
Responsible Party: Grandview Enterprises, Inc
Date Incident: 1/1/2011 **Time Incident:** 0830 **Duration:** 2 hours
County: Burleigh **Twp:** 139 **Rng:** 80 **Sec:** 25 **Qtr:**
Lat: 46.83073 **Long:** -100.72020 **Method:** Derived from TRS
Location Description: Near 4009 E. Divide Ave, Bismarck, ND.

Submitted By: Melvin Fischer **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person:

7708 NE 99th St
Vancouver, WA

Distance Nearest Occupied Building: 75 Feet

Type of Incident: Fuel tank-semi tractor

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 75.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Fuel tank leaking from Semi-tractor.

Risk Evaluation:

No risk

of Fatalities: 0

of Injuries: 0

Affected Medium:

Potential Environmental Impacts:

None

Action Taken or Planned:

Western Plains Consulting, mitigation contractor, absorbed product from street, transported fto City of Bismarckk for approved disposal.

Wastes Disposal Location: City of Bismarck Landill

Agencies Involved: NDDDES

