

General Environmental Incident Summary

Incident: 1452 **Date/Time Notice:** 6/14/2011 1000 **DEM Incident No:**
Responsible Party: American Crystal Sugar Company
Date Incident: 6/13/2011 **Time Incident:** 2200 **Duration:** 15 minutes
County: Pembina **Twp:** 159 **Rng:** 51 **Sec:** 14 **Qtr:**
Lat: 48.59303 **Long:** -97.17905 **Method:** Derived from TRS
Location Description: 8152 County Highway 44 North, Drayton, ND

Submitted By: Steve Lindquist **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Steve Lindquist
8152 County Highway 44 North
PO Box 190
Drayton, ND 58225-0190

Distance Nearest Occupied Building: 2 Miles

Type of Incident: Vehicle Accident

Description of Released Contaminant: Beet Molasses

Volume Spilled: 50.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

The Warehouse foreman on swing shift brought in his people who were working outside after a lightning strike in the yard. The person loading the rail tanker was not allowed to climb up onto the loading platform to shut off the loading. By the time the "all clear" was called, the tank had overflowed slightly.

Risk Evaluation:

None.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 04 - water and soil

Potential Environmental Impacts:

None.

Action Taken or Planned:

It rained heavily in the Drayton rinsing the area well. Some minor additional rinsing with a fire hose will be done to completely clean the site.

Wastes Disposal Location: The rinse water is captured in our ditch system and will be sent to our Mud Pond for treatment.

Agencies Involved: