

# General Environmental Incident Summary

**Incident:** 1535      **Date/Time Notice:** 10/3/2011      1215      **DEM Incident No:**  
**Responsible Party:** American Crystal Sugar Company  
**Date Incident:** 10/2/2011      **Time Incident:** 1115      **Duration:** 2 minutes  
**County:** Pembina      **Twp:** 162      **Rng:** 53      **Sec:** 36      **Qtr:** SE SE SE  
**Lat:** 48.81153      **Long:** -97.43615      **Method:** Derived from TRS  
**Location Description:** 1/2 mile east of intersection of ND 5 and US 81

**Submitted By:** Chad Wardner      **Affiliation:**

**Address:**

**City:**      **State:**      **Zip:**

**Received By:**

**Contact Person:** Chad Wardner  
8152 County Highway 44 North  
PO Box 190  
Drayton, ND 58225-0190

**Distance Nearest Occupied Building:** 0.75 Miles

**Type of Incident:** Tank Leak

**Description of Released Contaminant:** Diesel

**Volume Spilled:** 50.00 gallons      **Ag Related:** Yes

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

**Cause of Incident:**

Fuel line broke on a truck

**Risk Evaluation:**

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

All soil was excavated. Contained on concrete, and hauled to landfill.

**Wastes Disposal Location:** Landfill

**Agencies Involved:**

## ***Updates***

---

***Date:*** 10/5/2011

Comment

***Author:*** Harries, Alison

### ***Updated Volume:***

### ***Notes:***

sent of behalf of Chad Warner of American Crystal Sugar:

The recovered wastes were disposed at Refuse Disposal Landfill. Located 3 miles east of Grafton, ND and 2 miles south.