

General Environmental Incident Summary

Incident: 1820 **Date/Time Notice:** 11/16/2012 1018 **DEM Incident No:**

Responsible Party: EOG Resources

Date Incident: 11/15/2012 **Time Incident:** 1000 **Duration:** 15 minutes

County: Mountrail **Twp:** 151 **Rng:** 90 **Sec:** 4 **Qtr:** NW NE

Lat: 47.92713 **Long:** -102.20420 **Method:** Derived from TRS

Location Description: 1/2 mile west of junction of 75th Ave NW and 36th ST NW - EOG Location
Fertile 51-0410H

Submitted By: Danielle Dupay

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Danielle Dupay
6201 81st Ave NW
PO Box 639
Stanley, ND 58784

Distance Nearest Occupied Building:

Type of Incident: Hose Leak

Description of Released Contaminant: Treated Manufactured Salt Water

Volume Spilled: 1.50 barrels

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Treated Manufactured Salt Water hose to blender during Frac cracked, due to freezing of hose resulting in manufactured salt water leaking onto location onsite.

Risk Evaluation:

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Action Taken or Planned:

Vac truck was used to suck up standing liquid. Contaminated soil will be removed and taken to disposal after Frac complete.

Wastes Disposal Location: Clean Harbors, Sawyer ND

Agencies Involved:

Updates

Date: 11/27/2012 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Release occurred on location during a fracing operation. It remained on location according to the report, so it remains in O&G jurisdiction.