

General Environmental Incident Summary

Incident: 1827 **Date/Time Notice:** 11/27/2012 0230 **DEM Incident No:**

Responsible Party: Western Petroleum

Date Incident: 11/27/2012 **Time Incident:** 0230 **Duration:**

County: McKenzie **Twp:** 150 **Rng:** 94 **Sec:** 25 **Qtr:**

Lat: 47.78246 **Long:** -102.65320 **Method:** Derived from TRS

Location Description: Hwy 22 south of New Town, go 1/2 mile past Hwy 73, turn left. Follow WPX sign and stay left for 3.5 miles. Turn left and follow road to location

Submitted By: Bosko Guska

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Chris Teter
102 C45 Hwy 2
Tioga, ND 58852

Distance Nearest Occupied Building: 10 Miles

Type of Incident: Pump Leak

Description of Released Contaminant: #1 Clear Diesel Fuel

Volume Spilled: 150.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Driver was unloading fuel and the bands that hold the hose onto the outlet side of the pump came loose and caused fuel to leak on the ground

Risk Evaluation:

Soil Contamination

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Soil Contamination

Action Taken or Planned:

Driver, helper, and other parties immediately contained the spill and used absorbents to soak up the fuel. An environmental spill clean-up company was called in to excavate the contaminated soil and dispose of it properly

Wastes Disposal Location: Spill clean-up company will dispose of the soil, unknown location of disposal.

Agencies Involved:

Updates

Date: 11/27/2012 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

This is within MHA Nation boundaries.