

General Environmental Incident Summary

Incident: 1840 **Date/Time Notice:** 12/26/2012 1410 **DEM Incident No:**
Responsible Party: CHS Inc
Date Incident: 12/26/2012 **Time Incident:** 0730 **Duration:** 1 minutes
County: Grand Forks **Twp:** 151 **Rng:** 50 **Sec:** 31 **Qtr:** SW SW SW
Lat: 47.85318 **Long:** -97.09914 **Method:** Derived from TRS
Location Description: 7200 S 55th St, Grand Forks, ND 58201

Submitted By: Ben Renberg **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Ben Renberg
5500 Cenex Dr MS502
Inver Grove Heights, MN, MN 55077

Distance Nearest Occupied Building: 500 Feet

Type of Incident: Tank Overflow

Description of Released Contaminant: Clear Diesel

Volume Spilled: 10.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Electronic Monitor gave bad reading. Tank was overfilled with a small burp coming out the vent pipe with trickling for another 30 seconds. Estimate =>10 gals in a non-permeable containment field.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

none

Action Taken or Planned:

Waiting for the snow to melt and will use oil absorbant pads to collect fuel from water in containment

Wastes Disposal Location: Landfill

Agencies Involved:

Updates

Date: 12/26/2012 **Status:** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

This spill remained within synthetic lined tank dikes. Small amount, and plan for removal and collection is included. Grand Forks Health Department may inspect.