

# General Environmental Incident Summary

**Incident:** 1869      **Date/Time Notice:** 2/5/2013      0900      **DEM Incident No:**

**Responsible Party:** Badger Daylighting

**Date Incident:** 2/5/2013      **Time Incident:** 0900      **Duration:**

**County:** Stark      **Twp:** 139      **Rng:** 96      **Sec:** 10      **Qtr:**

**Lat:** 46.86873      **Long:** -102.77930      **Method:** Derived from TRS

**Location Description:** 958 East Broadway Dickinson, ND.....

**Submitted By:** ken Musick

**Affiliation:**

**Address:**

**City:**

**State:**

**Zip:**

**Received By:**

**Contact Person:** BJ Simons  
5301 poison spider rd.  
casper, WY 58601

**Distance Nearest Occupied Building:** 100 Feet

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** Diesel Fuel

**Volume Spilled:** 60.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** No

**Cause of Incident:**

Truck accident , ruptured fule tank spilling about 60 gallons of Diesel fuel on to street.

**Risk Evaluation:**

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:**

**Potential Environmental Impacts:**

**Action Taken or Planned:**

contained with floor dry. sweep off road. Badger Daylighting will collect and dispose of material

**Wastes Disposal Location:** Badger Daylighting will recover wastes

**Agencies Involved:** Local Fire Department, Local Law Enforcement, Local Emergency Manager

## **Updates**

---

**Date:** 2/5/2013    **Status:** Reviewed - No Action Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Local authorities responded and will oversee clean up.