

# General Environmental Incident Summary

**Incident:** 1913      **Date/Time Notice:** 5/2/2013      0946      **DEM Incident No:**  
**Responsible Party:** Bridger Transfer Services  
**Date Incident:** 4/30/2013      **Time Incident:** 0917      **Duration:** 1 minutes  
**County:** McKenzie      **Twp:** 152      **Rng:** 101      **Sec:** 19      **Qtr:** NW NW NW  
**Lat:** 47.97133      **Long:** -103.65850      **Method:** Derived from TRS  
**Location Description:** 14361 39th Street NW, Alexander, ND,  
58831

**Submitted By:** David LaMay      **Affiliation:**

**Address:**

**City:**      **State:**      **Zip:**

**Received By:**

**Contact Person:** Otis Randle  
800 Spring Street,  
suite 205  
Shreveport, LA 71101

**Distance Nearest Occupied Building:** 1 Miles

**Type of Incident:** oil release from trailer

**Description of Released Contaminant:** crude oil

**Volume Spilled:** 0.50 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

**Cause of Incident:**

unknown cause, oil found spilled on our location driveway

**Risk Evaluation:**

none

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

no run off or leaching happened, all waste was contained and remediated

**Action Taken or Planned:**

operator noticed oil in driveway and immediately called Outwest field services to clean up oil on site

**Wastes Disposal Location:** Outwest hauled away approximately 1 yd of waste to their yard to eventually dispose of with another load.

**Agencies Involved:**

**Updates**

---

**Date:** 5/6/2013    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Release due to tank trailer leak on facility driveway. Follow-up to confirm clean up is necessary.

---

**Date:** 5/8/2013    **Status:** Inspection

**Author:** Clary, Shane

**Updated Volume:**

**Notes:**

No signs of a spill on this location.