

# General Environmental Incident Summary

**Incident:** 1990      **Date/Time Notice:** 7/17/2013      1600      **DEM Incident No:**  
**Responsible Party:** North Dakota National Guard  
**Date Incident:** 7/15/2013      **Time Incident:** 1800      **Duration:** 1 hours  
**County:** McLean      **Twp:** 147      **Rng:** 85      **Sec:** 36      **Qtr:** SE NW NE  
**Lat:** 47.50931      **Long:** -101.45170      **Method:** Derived from TRS  
**Location Description:** Property owned by the US Army Corp of Engineers, leased by the North Dakota National Guard for training Area is known as the Douglas Creek Local Training Area

**Submitted By:** Ken Wangler      **Affiliation:**

**Address:**

**City:**      **State:**      **Zip:**

**Received By:**

**Contact Person:** Steve Herda  
PO Box5511  
Bismarck, ND 58506-5511

**Distance Nearest Occupied Building:** 3 Miles

**Type of Incident:** fuel filter crack leaked

**Description of Released Contaminant:** diesel fuel

**Volume Spilled:** 5.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** No

**Cause of Incident:**

filter cracked

**Risk Evaluation:**

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

none likely

**Action Taken or Planned:**

Unit shut off and filter replaced. All fuel stayed in the soil, none reached the water. 1/3 of a cubic yard was excavated and placed into sealed bags. When no additional odor of diesel was evident in the soil, the area was reclaimed as per instruction from Mr. Scott Stockdill with the ND Dept of Health.

**Wastes Disposal Location:** Minot City Landfill as municipal solid waste

**Agencies Involved:**

## **Updates**

---

**Date:** 7/17/2013    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to report follow up is required.

---

**Date:** 7/31/2013    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

N.) 47 36.010"  
W.) -101 34.505"

Site reclaimed and no more follow up is required. Minimal amount of damage and site is barely visible after two weeks.

No Follow up is necessary.