

# General Environmental Incident Summary

**Incident:** 2071      **Date/Time Notice:** 10/17/2013      1000      **DEM Incident No:**  
**Responsible Party:** Southern Energy Transportation  
**Date Incident:** 10/16/2013      **Time Incident:** 1000      **Duration:** 1 minutes  
**County:** McKenzie      **Twp:** 151      **Rng:** 101      **Sec:** 7      **Qtr:**  
**Lat:** 47.91338      **Long:** -103.65830      **Method:** Derived from TRS  
**Location Description:** Whiting Oil and Gas location, Taylor 14-7CTB, approximately 5 miles north of Alexander, ND west of Hwy 85

**Submitted By:** David LaMay      **Affiliation:**

**Address:**

**City:**      **State:**      **Zip:**

**Received By:**

**Contact Person:** Otis Randle  
15510 Wright Brothers Dr.  
Addison, TX 75001

**Distance Nearest Occupied Building:** 1 Miles

**Type of Incident:** trailer release

**Description of Released Contaminant:** crude oil

**Volume Spilled:** 30.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

**Cause of Incident:**

Driver released oil from out his vent line on his trailer

**Risk Evaluation:**

No immediate risks

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Oil was contained and all contaminated scoria rock driveway material has been excavated and removed from site.

**Action Taken or Planned:**

Driver immediately stopped pumping and contained the oil. He attempted to clean up the oil with pads. Field safety representatives responded to the release and assessed the situation. They called United States Environmental Services to begin clean up and disposal of waste.

**Wastes Disposal Location:** Prairie Disposal Facility

**Agencies Involved:**

**Updates**

---

**Date:** 10/18/2013 **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Relase occurred on an E&P location. Forwarding to O&G, Dave Hvinden.