

General Environmental Incident Summary

Incident: 2131 **Date/Time Notice:** 12/3/2013 1900 **DEM Incident No:**
Responsible Party: Nortwood Coop Oil
Date Incident: 12/2/2013 **Time Incident:** 1500 **Duration:** 10 minutes
County: Grand Forks **Twp:** 149 **Rng:** 54 **Sec:** 9 **Qtr:** SW SW NE
Lat: 47.73770 **Long:** -97.56989 **Method:** Interpolation from map
Location Description: 307 N ADAMS St, NORTHWOOD ND 58267

Submitted By: Chad Veer **Affiliation:** homeowner
Address: 307 N Adams St
City: Northwood **State:** ND **Zip:** 58267

Received By: David Cameron Health
Contact Person: Roger Korsmo
401 Hwy 15 W
Northwood, ND 58267

Distance Nearest Occupied Building: 1 Feet
Type of Incident: Spill- wrong address no tank
Description of Released Contaminant: Heating oil
Volume Spilled: 191.00 gallons **Ag Related:** No
EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:
Heating Oil delivered to wrong address. External fill not connected to anything. so all spilled into basement of home.

Risk Evaluation:
Health hazard- head aches from exposure to hydrocarbon fumes. Some fire risk but electricity turned off.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 05 - air and soil

Potential Environmental Impacts:
impacts localized to the area of the house. Soil/ groundwater under the basement floor.

Action Taken or Planned:
Fire and Police and City notified. Electricity turned off . Family has moved to apartment until house can be cleaned. Basement will be gutted and then condition of concrete floor assessed.

Wastes Disposal Location: construction demolition debris - disposal location unknown will be either Grand Forks landfill or Northwood inert site.

Agencies Involved: Local Fire Department, Local Law Enforcement

Updates

Date: 12/3/2013 **Status:** Reviewed - Assigned to NDDoH Division

Author: Cameron, Dave

Updated Volume:

Notes:

Assigned to Waste Management Division. Report forwarded to AST/UST team. Electricity restored 12/10. Cleanup will continue. PID readings of 1-3 ppm main floor, 15 ppm in sump in basement. No floor drain. Widseth SmithNolting will assess environmental impacts and monitor cleanup.