

# General Environmental Incident Summary

**Incident:** 2134      **Date/Time Notice:** 12/5/2013      1518      **DEM Incident No:**  
**Responsible Party:** Plains Marketing  
**Date Incident:** 12/5/2013      **Time Incident:** 1100      **Duration:** 1 minutes  
**County:** McKenzie      **Twp:** 151      **Rng:** 103      **Sec:** 11      **Qtr:**  
**Lat:** 47.90672      **Long:** -103.83570      **Method:** Interpolation from map  
**Location Description:** 8 miles north of Cartwright, ND, at an oil well tank battery location.

**Submitted By:** Daniel Holli      **Affiliation:**  
**Address:** P.O. Box 708  
**City:** Belfield      **State:** ND      **Zip:** 58622

## Received By:

**Contact Person:** Daniel Holli  
P.O. Box 708  
Belfield, ND 58622

**Distance Nearest Occupied Building:** 0.5 Miles

**Type of Incident:** Truck overfill

**Description of Released Contaminant:** Crude Oil

**Volume Spilled:** 2.00 barrels

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

## Cause of Incident:

Driver pushed oil out truck vent line.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soil impact

## Action Taken or Planned:

Soil was scraped up onto plastic pending disposal

**Wastes Disposal Location:** Sawyer landfill

**Agencies Involved:** NDDDES

## **Updates**

---

**Date:** 12/5/2013    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the company contact, this incident occurred at a the Zavanna Skorpil 11-2-1H Well location. NDIC has oversight. Report forwarded to NDIC O&G Division.