

# General Environmental Incident Summary

**Incident:** 2158      **Date/Time Notice:** 12/30/2013      1242      **DEM Incident No:**

**Responsible Party:** Unknown

**Date Incident:** 12/29/2013      **Time Incident:** 1030      **Duration:** 5 hours

**County:** Mountrail      **Twp:** 155      **Rng:** 92      **Sec:** 20      **Qtr:**

**Lat:** 48.22680      **Long:** -102.54330      **Method:** Calculated

**Location Description:** From Ross, ND, West on Hwy 2 to 90th st., South on 90th Ave NW approximately 6 miles to 56th st. East on 56th st approximately .5 mile and the location is on the north side of the road.

**Submitted By:** Jeremy Mohl

**Affiliation:**

**Address:** 514 W. Broadway

**City:** Williston

**State:** ND

**Zip:** 58801

**Received By:**

**Contact Person:**

Unknown

Williston, ND

**Distance Nearest Occupied Building:** 1 Miles

**Type of Incident:** Poly tank lines leaking due to damage

**Description of Released Contaminant:** Methanol

**Volume Spilled:** 33.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Yes

**Reported to NRC:** No

**Cause of Incident:**

An unknown vehicle backed into the poly methanol tanks used to supply a production compressor station on the location. As a result of the incident, the 1/8 inch lines were stretched and began to leak. The containment system that the poly tank is in also cracked. The methonal leaked into the containment out the crack causing approximately 33 gallons to be released to the ground.

**Risk Evaluation:**

There was an initial risk of explosion at the point the vehicle contacted the tanks due to the flammable nature of the methonal.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

There are no expected impacts to the environment due to the remediation of contaminated soil.

**Action Taken or Planned:**

The methonal was transfered from the poly tanks into 55 gallon drums to prevent any further leaking and the released product was 100% recovered.

**Wastes Disposal Location:** Prairie Disposal

**Agencies Involved:**

## **Updates**

---

**Date:** 12/30/2013 **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the report, the surrounding area was impacted by the spilled material. Followup necessary.

---

**Date:** 12/31/2013 **Status:** Inspection

**Author:** Miller, Adam

**Updated Volume:**

**Notes:**

Well name is Cvancara 20-17/Sorenson 29-32 (Statoil). Location is being actively drilled by Nabors. Spill remained on location. NDIC retains oversight.