

# General Environmental Incident Summary

**Incident:** 2165      **Date/Time Notice:** 1/7/2014      0930      **DEM Incident No:**  
**Responsible Party:** CHS  
**Date Incident:** 12/30/2013      **Time Incident:** 0750      **Duration:** 5 minutes  
**County:** Williams      **Twp:** 159      **Rng:** 97      **Sec:** 21      **Qtr:** SE SE SE  
**Lat:** 48.57552      **Long:** -103.21190      **Method:** Navigation quality GPS  
**Location Description:** ND Hwy 50 and 117 Ave NW approximately 13 miles west of McGregor, ND

**Submitted By:** Eric Pearson      **Affiliation:** CHS  
**Address:** 4115 27th Ave N  
**City:** Grand Forks      **State:** ND      **Zip:** 58203

## Received By:

**Contact Person:** ERic Pearson  
4115 27th Ave N  
Grand Forks, ND 58203

## Distance Nearest Occupied Building:

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** Diesel Fuel

**Volume Spilled:** 50.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Yes

## Cause of Incident:

Vehicle (#2 semi hauling gravel/dirt) pulled out of side road onto Hwy 50 in front of CHS contracted vehicle (#1 semi hauling fuel). Vehicle #1 struck vehicle #2 near the rear axels causing damage to vehicle #1. Vehicle #1 went into the ditch approximately 100 feet. The fuel tank of Vehicle #1 was damaged as was the oil pan. approximately 45-50 gallons of fuel was spilled along with approximately 10 gallons of oil. No spill occurred from the fuel trailer.

## Risk Evaluation:

none

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

none

## Action Taken or Planned:

Spill was contained in the ditch and was minimally spread due to the snow. CHS contracted with a third party to bring a loader and container truck to scrape (frozen ground) the area from where the truck entered the ditch to the resting spot of the semi removing any spilled material.

**Wastes Disposal Location:** material will be disposed of at a local landfill more than likely Clean Harbors.

**Agencies Involved:** Local Law Enforcement

**Updates**

---

**Date:** 1/7/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the spill report, this incident impacted the surrounding area. Followup is necessary.

---

**Date:** 1/8/2014    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

Arrived on location at 13:24 1/8/14.

No sign of vehicle accident at described location.

Follow-up phone call is necessary to ensure complete cleanup.

---

**Date:** 7/11/2014    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

Further site inspections have shown no negative signs of spill from this incident.

No followup is necessary.