

General Environmental Incident Summary

Incident: 3211 **Date/Time Notice:** 2/24/2014 1515 **DEM Incident No:**
Responsible Party: Pilot Travel Centers
Date Incident: 2/23/2014 **Time Incident:** 1500 **Duration:** 5 minutes
County: Williams **Twp:** 156 **Rng:** 101 **Sec:** 12 **Qtr:**
Lat: 48.34380 **Long:** -103.61680 **Method:** Interpolation from map
Location Description: 13553 64th Street, Williston, ND

Submitted By: Max Burmeister **Affiliation:**
Address: 9874 Main Street
City: Woodstock **State:** GA **Zip:** 30188

Received By:

Contact Person: Joey Cupp
5508 Lonas Road
Knoxville, TN 37909

Distance Nearest Occupied Building:

Type of Incident: Tank Overflow

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 10.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Driver overfilled the USTs causing fuel to overflow out of the vent stacks. Approximately 10 gallons was spilled onto the frozen grass surface.

Risk Evaluation:

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Action Taken or Planned:

Fuel was cleaned up from the surface and additional clean up does not appear to be warranted at this time.

Wastes Disposal Location: Placed in 55 gallon drums for disposal at a later date. Typically Safety Kleen.

Agencies Involved:

Updates

Date: 2/24/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release, due to tank overflow, was to a grassed area. Followup is necessary.

Date: 3/17/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location at 12:25 3/6/14.

Floor Dry placed on top of spill, and vent area has been roped off.

No followup is necessary due to a minimal amount of area impacted and the impermeability of the impacted surface.