

# General Environmental Incident Summary

**Incident:** 3272      **Date/Time Notice:** 3/31/2014      0745      **DEM Incident No:**  
**Responsible Party:** TAQA North  
**Date Incident:** 3/30/2014      **Time Incident:** 13:00      **Duration:** 4 hours  
**County:** Renville      **Twp:** 164      **Rng:** 85      **Sec:** 35      **Qtr:** SE SE NW  
**Lat:** 48.98970      **Long:** -101.66550      **Method:** Interpolation from map  
**Location Description:** Celestine / Volk #1 Battery

**Submitted By:** Kevin Thompson      **Affiliation:** Production Foreman  
**Address:** 548 W Boundary  
**City:** Plentywood      **State:** MT      **Zip:** 59254

## Received By:

**Contact Person:** Joanne Germaine  
2100 308 4th ave SW  
Calgary, AB T2P0H7

**Distance Nearest Occupied Building:** 2 Miles      **Release Contained:** Yes

**Type of Incident:** Pump Leak

**Description of Released Contaminant:** Salt water/ oil

**Volume Spilled:** 50.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Yes

## Cause of Incident:

Fiberglass line to the injection pump failed

## Risk Evaluation:

Soil contamination

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soil contamination contained on site, mostly within the bermed area. Estimated 10 bbls outside bermed area - contained on site

## Action Taken or Planned:

Shut off production and isolated tanks/pump

**Wastes Disposal Location:** To be determined / Secure energy

## Agencies Involved:

## **Updates**

---

**Date:** 3/31/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Release, due to a pump leak, remained on location inside and outside the tank containment dike. NDIC retains oversight. Report forwarded to NDIC.