

General Environmental Incident Summary

Incident: 3281 **Date/Time Notice:** 4/9/2014 1711 **DEM Incident No:**
Responsible Party: Plains Pipeline
Date Incident: 4/8/2014 **Time Incident:** 1400 **Duration:** 1 days
County: Bowman **Twp:** 132 **Rng:** 107 **Sec:** 27 **Qtr:**
Lat: 46.22186 **Long:** -104.03970 **Method:** Navigation quality GPS
Location Description: 10 miles south of Marmarth on Camp Crook Rd then 10 miles northwest on gravel roads

Submitted By: Daniel Holli **Affiliation:**
Address: P.O. Box 708
City: Belfield **State:** ND **Zip:** 58622

Received By:

Contact Person: Daniel Holli
P.O. Box 708
Belfield, ND 58622

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: valve seep

Description of Released Contaminant: Crude Oil

Volume Spilled: 0.50 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

A valve seeped resulting in a mist of oil on adjacent piping and ground.

Risk Evaluation:

none

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

soil

Action Taken or Planned:

Valve was replaced and contaminated soil scraped up.

Wastes Disposal Location: Hexom Indian Hills Landfarm

Agencies Involved:

Updates

Date: 4/9/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Pipeline valve leak resulting in spray of oil to the ground. Followup is necessary.

Date: 6/9/2015 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

6/9/2015 at 18:24, on location. Site is ESE of Continental Resource's Bradac #34-27H (NDIC #13981). Pipeline risers fenced in, no visible staining outside of the fencing. One pipe fitting has some old staining visible beneath it, however this is within the center of the fenced area.