

# General Environmental Incident Summary

**Incident:** 3291      **Date/Time Notice:** 4/16/2014      **DEM Incident No:**

**Responsible Party:** American Crystal Sugar Company

**Date Incident:** 4/16/2014      **Time Incident:**      **Duration:**

**County:** Walsh      **Twp:** 155      **Rng:** 52      **Sec:** 32      **Qtr:**

**Lat:** 48.20500      **Long:** -97.35596      **Method:** Interpolation from map

**Location Description:** Ardoch Coal Handling and Storage Facility  
5468 151 Avenue NE  
Ardoch, ND 58261  
(701) 248-3160

**Submitted By:** Annette Cederberg

**Affiliation:** American Crystal Sugar Company

**Address:** 101 North Third Street

**City:** Moorhead

**State:** MN

**Zip:** 56560

## Received By:

**Contact Person:** Annette Cederberg  
101 North Third Street  
Moorhead, MN 56560

**Distance Nearest Occupied Building:** 0.05 Miles

**Release Contained:** Yes

**Type of Incident:** Tank Leak

**Description of Released Contaminant:** Anti-freeze and small amount of oil

**Volume Spilled:** 20.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

## Cause of Incident:

BNSF locomotive engine leak

## Risk Evaluation:

none

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

## Potential Environmental Impacts:

none

## Action Taken or Planned:

Free liquid recovered and any contaminated soils removed.

**Wastes Disposal Location:** Land spread on-site or landfilled.

## Agencies Involved:

## ***Updates***

---

***Date:*** 4/16/2014    ***Status:*** Reviewed - Assigned to NDDoH Division

***Author:*** Roberts, Kris

### ***Updated Volume:***

### ***Notes:***

Release of antifreeze and oil from locomotive engine. Followup by phone or inspection is necessary. Referred to NDDoH Waste Management.