

# General Environmental Incident Summary

**Incident:** 3295      **Date/Time Notice:** 4/18/2014      1530      **DEM Incident No:**  
**Responsible Party:** Danco Transport  
**Date Incident:** 4/17/2014      **Time Incident:** 1830      **Duration:** 2 minutes  
**County:** McKenzie      **Twp:** 150      **Rng:** 99      **Sec:** 24      **Qtr:** NE  
**Lat:** 47.79815      **Long:** -103.28450      **Method:** Interpolation from map  
**Location Description:** 202 3rd Ave. SW, Watford City, ND 58854 (East Lot)

**Submitted By:** Leigh Jennings      **Affiliation:** Rolfson Oil, LLC, Corporate Couns  
**Address:** 124 E. Fulton St.  
Suite 404  
**City:** Grand Rapids      **State:** MI      **Zip:** 49503

## Received By:

**Contact Person:** Dan  
6958 River Rd. SE  
Clear Lake, MN 55319

**Distance Nearest Occupied Building:** 100 Feet      **Release Contained:** No  
**Type of Incident:** driver's hose blew apart  
**Description of Released Contaminant:** diesel fuel  
**Volume Spilled:** 400.00 gallons      **Ag Related:** No  
**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

Driver from Danco Transport was loading fuel and failed to open value to tanks. He blew up his hose and fuel spilled around the truck and down a hill on Rolfson property.

## Risk Evaluation:

No immediate health risks, potential fire hazard.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soil impacted at site, and potential water impact as fuel was released on the ground. Clean up is continuing at this time.

## Action Taken or Planned:

Pig blankets used to absorb as much as possible. Absorbent called to do clean up and disposal of contaminated soil.

**Wastes Disposal Location:** Absorbent will properly dispose of contaminated soil.

## Agencies Involved:

## **Updates**

---

**Date:** 4/18/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

### **Updated Volume:**

#### **Notes:**

Release, due to blown delivery hose, impacted city street and ran down into the Rolfson Oil facility. Followup is necessary.

---

**Date:** 4/23/2014    **Status:** Inspection

**Author:** Roberts, Kris

### **Updated Volume:**

#### **Notes:**

4/23/14 - 09:30 on location. This and two other reported release at this location were inspected. This release, due to the blown hose, was on to the street outside the facility and had been cleaned up by removal of impacted gravel removal and replacement. Rolfson Oil is under assessment and cleanup order from the department. Bill Sues, Groundwater Program is overseeing.