

# General Environmental Incident Summary

**Incident:** 3365      **Date/Time Notice:** 6/25/2014      0945      **DEM Incident No:**  
**Responsible Party:** Cypress Energy Partners  
**Date Incident:** 6/20/2014      **Time Incident:** 0748      **Duration:** 2 minutes  
**County:** McKenzie      **Twp:** 150      **Rng:** 100      **Sec:** 13      **Qtr:** SE SE  
**Lat:** 47.80752      **Long:** -103.41480      **Method:** Interpolation from map  
**Location Description:** SBG Arnegard Facility (aka Alati Arnegard SWD)

**Submitted By:** Jeff English      **Affiliation:** VP-Operations  
**Address:** 5727 South Lewis Avenue  
Suite 500  
**City:** Tulsa      **State:** OK      **Zip:** 74105

## Received By:

**Contact Person:** Jeff English  
5727 South Lewis Avenue  
Suite 500  
Tulsa, OK 74105

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** Pump Leak

**Description of Released Contaminant:** Produced Brine Water

**Volume Spilled:** 10.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

Water hauler disconnected hose from offload lane while it was still under pressure and caused produced brine water to spill off of truck until the pump was turned off.

## Risk Evaluation:

There were no immediate risks as a result of this spill.

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

The spill was contained on our pad site location and did not drain anywhere off of the pad site. All contaminated materials were collected and disposed of properly.

## Action Taken or Planned:

Majority of the liquid was captured at the concrete offload lane and it was sucked back up by the water hauler. There was approximately a 10' area off of the concrete offload lane that had produced brine water on the surface area and we used our spill kit dippers to contain this liquid. We used a bobcat to scrape the dirt and it was hauled off for disposal by Black Shirt Trucking to Indian Hills Disposal. We replaced the area with fresh scoria.

**Wastes Disposal Location:** Black Shirt Trucking hauled the material off to Indian Hills Disposal.

**Agencies Involved:**

**Updates**

---

**Date:** 7/7/2014      **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Release, due to an on-location pump leak, remained on location according to the report. NDIC retains oversight. Forwarded to NDIC.