

General Environmental Incident Summary

Incident: 3378 **Date/Time Notice:** 7/8/2014 11:44 **DEM Incident No:**

Responsible Party: Arrow Pipeline, LLC

Date Incident: 7/8/2014 **Time Incident:** 11:44 **Duration:**

County: McKenzie **Twp:** 150 **Rng:** 94 **Sec:** 25 **Qtr:**

Lat: 47.78473 **Long:** -102.64400 **Method:** Navigation quality GPS

Location Description: pipeline valve station

Submitted By: Don Butler

Affiliation: Director, Environmental and Regula

Address: 801 Cherry Street

Suite 3800/Unit 20

City: Fort Worth

State: TX

Zip: 76102

Received By:

Contact Person: Don Butler
801 Cherry Street
Suite 3800/Unit 20
Fort Worth, TX 76102

Distance Nearest Occupied Building:

Release Contained: No

Type of Incident: Pipeline Leak

Description of Released Contaminant: Saltwater (brine), crude oil condensate

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Yes

Cause of Incident:

Equipment malfunction

Risk Evaluation:

None

of Fatalities:

of Injuries:

Affected Medium: 04 - water and soil

Potential Environmental Impacts:

surface water, soils

Action Taken or Planned:

Release being contained, control countermeasures being deployed, fluid planned to be evacuated from area, as conditions permit, further remedial measures being considered currently.

Wastes Disposal Location:

Agencies Involved: Local Law Enforcement, Local Emergency Manager, BIA/BLM. TAT

Updates

Date: 7/9/2014

Status: Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

7/8/14 - 15:30+- on location at invitation of MHA Environmental. Water in drainage downslope of road was at 216,000 uS/cm. MHA is in the lead on this. US EPA OSC Pete Stevenson is deploying to location 7/9/2014.