

General Environmental Incident Summary

Incident: 3404 **Date/Time Notice:** 7/28/2014 **DEM Incident No:**
Responsible Party: D&L Construction
Date Incident: 7/27/2014 **Time Incident:** 1132 **Duration:** 10 minutes
County: Mountrail **Twp:** 152 **Rng:** 90 **Sec:** 15 **Qtr:** NW NW
Lat: 48.13361 **Long:** -102.32440 **Method:** Navigation quality GPS
Location Description: From ND Highway 23, 1 mile north on 74th Avenue NW, then west on 40th Street NW on mile
Submitted By: Donald Lonmguir **Affiliation:** Mountrail County Disaster Emergen
Address: P.O. Box 248
8103 61st Street NW
City: Stanley **State:** ND **Zip:** 58784-0248

Received By:

Contact Person: Devin Johnson
P.O. Box 424
Parshall, ND 58770-0424

Distance Nearest Occupied Building: 0.5 Miles **Release Contained:** Yes

Type of Incident: hydraulic hose break

Description of Released Contaminant: hydraulic fluid

Volume Spilled: 15.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** No

Cause of Incident:

Hydraulic hose broke on a water truck spraying water on the gravel road.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

None

Action Taken or Planned:

D&L Construction, Parshall, ND scrapped the material from the road

Wastes Disposal Location: D&L Construction disposed of the material

Agencies Involved: Local Emergency Manager, Three Affiliated Tribes

Updates

Date: 7/28/2014 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Hydraulic line leak. Release was contained and removed. No followup is necessary.