

# General Environmental Incident Summary

**Incident:** 3409      **Date/Time Notice:** 8/1/2014      **DEM Incident No:**  
**Responsible Party:** Corissa Zimmer  
**Date Incident:** 7/30/2014      **Time Incident:**      **Duration:** 1 hours  
**County:** McKenzie      **Twp:** 149      **Rng:** 99      **Sec:** 17      **Qtr:** NW NE  
**Lat:** 47.73157      **Long:** -103.37940      **Method:** Navigation quality GPS  
**Location Description:** From Watford City head east on 2nd Ave NW towards Main St. Take the first right on Main and continue on US 85 S. Turn right onto Co Rd 30/23rd St NW and then turn right onto 22nd St NW and the destination will be on the left in half a mile.  
**Submitted By:** Corissa Zimmer      **Affiliation:**  
**Address:** 701 4th Ave NW  
**City:** Watford City      **State:** ND      **Zip:** 58854

## Received By:

### Contact Person:

701 4th Ave NW  
Watford City, ND 58854

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** Overflowed getty box

**Description of Released Contaminant:** Crude oil

**Volume Spilled:** 1.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

### Cause of Incident:

Transportation's failure to completely close a load line valve resulted in valve dripping which overflowed the getty box, although spilled oil (one barrel or less) remained within the tank battery berm.

### Risk Evaluation:

None known, immediately contained and cleaned up.

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

### Potential Environmental Impacts:

None known, immediately contained and cleaned up.

### Action Taken or Planned:

Fluid was sucked up and contaminated soil was removed.

### Wastes Disposal Location:

### Agencies Involved:

## **Updates**

---

**Date:** 8/1/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

This release, inside an oil E&P location containment, is being referred to NDIC for followup.

---

**Date:** 8/18/2014    **Status:** Inspection

**Author:** Wax, Pete

**Updated Volume:**

**Notes:**

On site 17:55; off site 18:55. Clear, 85 degrees, nw wind light. Site description should be: KUNNER 1431 CTB Twp 149, Rng 99, Sec 31, SW/SW. Pipeline row going west is clean and well shaped through the wheat field. Secondary reshaping on side of well pad also clean.