

# General Environmental Incident Summary

**Incident:** 3442      **Date/Time Notice:** 8/31/2014      130p      **DEM Incident No:**

**Responsible Party:** western choice coop.

**Date Incident:** 8/31/2014      **Time Incident:** 0500      **Duration:** 2 hours

**County:** Dunn      **Twp:** 146      **Rng:** 95      **Sec:** 20      **Qtr:**

**Lat:** 47.44446      **Long:** -102.81730      **Method:** Interpolation from map

**Location Description:** killdeer north on hwy 22 for 5 miles to mile marker 112 go east on second for 100 yards site is on south of road

**Submitted By:** jade ziman

**Affiliation:** energy manager

**Address:** 200 rodeo dr

**City:** killdeer

**State:** ND

**Zip:** 58640

## Received By:

**Contact Person:** jade ziman  
200 roedo drive  
killdeer, ND 58640

**Distance Nearest Occupied Building:** 2 Miles

**Release Contained:** Yes

**Type of Incident:** Tank Leak

**Description of Released Contaminant:** red dyed #2 diesel

**Volume Spilled:** 15.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

## Cause of Incident:

shoulder gave way and truck rolled

## Risk Evaluation:

none

**# of Fatalities:**

**# of Injuries:**

**Affected Medium:** 02 - water

## Potential Environmental Impacts:

none

## Action Taken or Planned:

dam was built in water, and pig mat was put where drips were coming from hatches vac truck was used to remove all water that was in dam

## Wastes Disposal Location:

**Agencies Involved:** Local Emergency Manager

## **Updates**

---

**Date:** 8/31/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Truck rollover into water body. Follow-up is necessary.

---

**Date:** 9/2/2014    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

Received call from company that the accident area has been cleaned up.

---

**Date:** 9/2/2014    **Status:** Reviewed - Follow-up Required

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

Release due to vehicle accident. Followup is necessary.

---

**Date:** 9/3/2014    **Status:** Inspection

**Author:** Tintes Schiwal, Emily

**Updated Volume:**

**Notes:**

I inspected the accident site at 11:30 on 09/03/14. Tracks led to the ditch, and soil disturbance was obvious. It appears that most of the diesel was cleaned up. There was no evidence of fuels in the standing ditch water, but there was a faint fuel smell and a small area of black staining in the dirt. Photos in corresponding folder.

---