

General Environmental Incident Summary

Incident: 3447 **Date/Time Notice:** 9/3/2014 **DEM Incident No:**

Responsible Party: JTW Trucking

Date Incident: 8/7/2014 **Time Incident:** **Duration:**

County: Stark **Twp:** 139 **Rng:** 96 **Sec:** 3 **Qtr:**

Lat: 46.87813 **Long:** -102.77900 **Method:** Interpolation from map

Location Description: West Dakota Oil C-Store

Submitted By: Duane Zastoupil

Affiliation:

Address: 3411 Public Works Blvd

City: Dickinson

State: ND

Zip:

Received By:

Contact Person: Jeff Jacobson
107 2nd ave E
Dickinson, ND

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 80.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Semi, came to West Dakota Oil, to fuel up. He had 2 tanks on his semi, he fueled one side then the other, and forgot to turn the pump off and put the hose back. His trailer drove over the hose which caused the pump to continue pumping fuel onto the ground until max dollar on pump was reached, or 230 gallons of diesel. His tanks could hold max of 150 gallons. Approximately 80 gallons of fuel spilled onto the ground and down the street into the storm drain and into the drainage ditch.

Risk Evaluation:

possible fire

of Fatalities:

of Injuries:

Affected Medium: 04 - water and soil

Potential Environmental Impacts:

I walked the drainage ditch, and didn't see any likelihood of any impact to the environment.

Action Taken or Planned:

Duane Zastoupil, and Brian Sukup, arrived at site. We noted that they had the spill at site covered with floor dry, and was in the process to remove the soil that was contaminated. We located the spill which entered the storm and in the drainage ditch, which we put out oil only socks to contain the fuel from entering the river. After we had the fuel spill contained we had the responsible party (JTW Trucking) call a clean up crew(Mirror Image) to clean up the spill. JTW Trucking Called Mirror Image of Dickinson, which came out and cleaned the storm drains and and cleaned out all the fuel from the

drainage ditch. After the spill was cleaned up I (Duane Zastoupil) inspected the storms drains, drainage ditch, and Outfall 31 to the River. I didn't see any signs of fuel in the storm drains, drainage ditch, and outfall 31 to river.

Wastes Disposal Location: Mirror Image took care of wastes

Agencies Involved:

Updates

Date: 9/3/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release at a fueling station. Follow-up is necessary.

Date: 9/5/2014 **Status:** Inspection

Author: Martin, Russell

Updated Volume:

Notes:

Report from responsible party for incident. For inspection report, see original incident ID 3416 filed by facility for incident location.

Date: 9/30/2015 **Status:** Inspection

Author: Suess, Bill

Updated Volume:

Notes:

This is a duplicate report. Incident number 3416 has been closed. Visited site and found no indication of impacts or adverse conditions.