

General Environmental Incident Summary

Incident: 3450 **Date/Time Notice:** 9/9/2014 1912 **DEM Incident No:**
Responsible Party: Emerald Oil, Inc.

Date Incident: 9/9/2014 **Time Incident:** 0630 **Duration:** 30 minutes

County: McKenzie **Twp:** 149 **Rng:** 102 **Sec:** 10 **Qtr:** SW SE

Lat: 47.73327 **Long:** -103.72650 **Method:** Navigation quality GPS

Location Description: CAPER 2-15-22H, CAPER 3-15-22H & CAPER 4-15-22H (CAPER WEST PAD)
SECTION 10, T149N, R102W, 5th P.M.
PROCEED IN A SOUTHERLY DIRECTION FROM ALEXANDER, NORTH DAKOTA ALONG ND-200/US-85 APPROXIMATELY 2.6 MILES TO THE JUNCTION OF THIS ROAD AND ND-86 W TO THE SOUTH; TURN RIGHT AND PROCEED IN A SOUTHERLY DIRECTION APPROXIMATELY 5.1 MILES TO THE JUNCTION OF THIS ROAD AND 22ND STREET NW TO THE WEST; TURN RIGHT AND PROCEED IN A WESTERLY DIRECTION APPROXIMATELY 3.6 MILES TO THE BEGINNING OF THE PROPOSED ACCESS TO THE NORTH; FOLLOW ROAD FLAGS IN A NORTHERLY, THEN WESTERLY DIRECTION APPROXIMATELY 338' TO THE PROPOSED LOCATION. TOTAL DISTANCE FROM ALEXANDER, NORTH DAKOTA TO THE PROPOSED WELL LOCATION IS APPROXIMATELY 11.4 MILES.

Submitted By: Rachael Overbey **Affiliation:** Emerald Oil Staff

Address: 1600 Broadway
Suite 1360

City: Denver **State:** CO **Zip:** 80202

Received By:

Contact Person: David Veltri
1600 Broadway
Suite 1360
Denver, CO 80202

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Produced Water Spill - Skim Oil

Description of Released Contaminant: Produced water and skim oil

Volume Spilled: 15.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

3rd party trucking company driver fell asleep while loading produced water on well pad location. Spill occurred on a 3 well pad; Caper 2-15-22H (file # 26261), Caper 3-15-22H (file # 26262) and Caper 4-15-22H (file # 26263).

Risk Evaluation:

None

of Fatalities: 0 ***# of Injuries:*** 0 ***Affected Medium:*** 09 - other

Potential Environmental Impacts:

None

Action Taken or Planned:

Hydrovac truck all collected all standing fluids. Back hoe removed affected top soil. SW and soils were trucked to appropriate disposal. New top soil and scoria will be laid on location.

Wastes Disposal Location: Trucked to disposal; Indian Hills Disposal

Agencies Involved:

Updates

Date: 9/9/2014 ***Status:*** Reviewed - Assigned to Other Agency ***Author:*** Roberts, Kris

Updated Volume:

Notes:

Release, due to truck overflow, on the Caper 2-15-22H well pad. NDIC retains oversight. Report forwarded to NDIC.