

General Environmental Incident Summary

Incident: 3482 **Date/Time Notice:** 10/1/2014 **DEM Incident No:**

Responsible Party: MATBUS

Date Incident: 9/30/2014 **Time Incident:** 17:00 **Duration:**

County: Cass **Twp:** 139 **Rng:** 49 **Sec:** 1 **Qtr:**

Lat: 46.88309 **Long:** -96.81666 **Method:** Interpolation from map

Location Description: 650 23rd St N, Fargo, ND 58102

Submitted By: Hunter Hubrig

Affiliation: Fargo Cass Public Health

Address: 4630 15th Ave N

City: Fargo

State: ND

Zip: 58102

Received By:

Contact Person:

650 23rd St N
Fargo, ND 58102

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 35.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Overflow of fuel tank on bus.

Risk Evaluation:

Fargo Fire Dept checked atmosphere levels in shop. Fargo Water Treatment Plant notified as precaution as it was uncertain if any fuel released into storm sewer.

of Fatalities:

of Injuries:

Affected Medium: 06 - water and air

Potential Environmental Impacts:

Not likely.

Action Taken or Planned:

Fuel released into catch basin in shop. Street Department with City of Fargo brought in a vac truck to remove diesel fuel that was in catch basin.

Wastes Disposal Location:

Agencies Involved: Local Fire Department

Updates

Date: 10/13/2014 **Status:** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release into catch basin inside building. City of Fargo departments followed up. No on-site inspection needed.