

General Environmental Incident Summary

Incident: 3507 **Date/Time Notice:** 10/16/2014 1600 **DEM Incident No:**

Responsible Party: Targa Resources

Date Incident: 10/14/2014 **Time Incident:** 1043 **Duration:**

County: McKenzie **Twp:** 150 **Rng:** 96 **Sec:** 24 **Qtr:** NW NW

Lat: 47.80265 **Long:** -102.91870 **Method:** Interpolation from map

Location Description: One mile east of the Highway 73 and McKenzie County Road 53 (i.e. Johnsons Corner).

Submitted By: Mark Glaser

Affiliation: Targa Resources

Address: 1939 125th Ave W

City: Watford City

State: ND

Zip: 58854

Received By:

Contact Person: Mark Glaser
1939 125th Ave W
Watford City, ND 58854

Distance Nearest Occupied Building: 1750 Feet

Release Contained: Yes

Type of Incident: Valve leak on tanker truck

Description of Released Contaminant: Crude Oil

Volume Spilled: 25.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

During oil load out within the truck loading rack at the Targa Resources Johnsons Corner Crude Oil Terminal, pressure from the oil in the tank caused a rupture on the flange directly in front of the quarter turn isolation valve. The valve that failed was part of the equipment on the tractor trailer on location to load and haul oil for Targa.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

None, Oil was contained within the truck loading rack driving lane.

Action Taken or Planned:

After the spill occurred the crude oil terminal operator was notified and dispatched get a spill clean-up response team to evaluate and begin cleaning the contained spill. The lanes were isolated and clean-up work began around 4:30pm. The response team had Lane 2 cleaned and reopened at 9:15pm and Lane 3 at 9:40pm.

Wastes Disposal Location: Wastes are stock piled and contained at Targa Resources Crude Oil Terminal. Once wastes have been analyzed and profiled they will be

hauled to a disposal facility approved by the NDDH and Targa Resources, i.e. PDI, Indian Hills, Sawyer disposal.

Agencies Involved:

Updates

Date: 10/16/2014 ***Status:*** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill occurred off of an E&P location. Followup is necessary.

Date: 10/21/2014 ***Status:*** Awaiting Documentation

Author: Cooper, Mike

Updated Volume:

Notes:

Arrived on site at 15:45 CT. Temperature 72 degrees, Wind 5-10mph NW. The site contact met me at the location and described the extent of the spill. Excavation of the site has been completed, and the contaminated material was left on site in a 25-yd roll-off box and is awaiting disposal and analyticals. The material will be hauled to PDI. No visible seepage was noticed during the inspection, indicating maximum effect of cleanup. Site contact will notify NDDoH representative when material is hauled away for disposal.