

# General Environmental Incident Summary

**Incident:** 3545      **Date/Time Notice:** 11/11/2014      1342      **DEM Incident No:**  
**Responsible Party:** Crestwood Crude Trans  
**Date Incident:** 11/10/2014      **Time Incident:**      **Duration:** 3 minutes  
**County:** Williams      **Twp:** 159      **Rng:** 95      **Sec:** 14      **Qtr:**  
**Lat:** 48.60369      **Long:** -102.91050      **Method:** Interpolation from map  
**Location Description:** Watterud 160-95-14A-23-2H North of McGreger ND in Divide Co, one mile east of the Jct. of 104th Ave and 88th St  
**Submitted By:** Joe Hoffart      **Affiliation:** Crestwood Crude  
**Address:** PO Box 646 12590 23rd St  
**City:** Watford City      **State:** ND      **Zip:** 58854

**Received By:**

**Contact Person:** Joe Hoffart  
PO Box 646 12590 23rd St NW  
Watford City, ND 58854

**Distance Nearest Occupied Building:**      **Release Contained:** No

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** Crude Oil

**Volume Spilled:** 20.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

**Cause of Incident:**  
Driver over filled front compartment on trailer

**Risk Evaluation:**  
No smoking, keep other vehicles from driving through

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**  
soil on pad

**Action Taken or Planned:**  
Soil excavated, by Absorbent & Safety Solutions, Oil contained on pad

**Wastes Disposal Location:**  
**Agencies Involved:**

## **Updates**

---

**Date:** 11/11/2014 **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the incident summary, this spill occurred on an E & P exempt location. Oversight falls to NDIC.