

General Environmental Incident Summary

Incident: 3598 **Date/Time Notice:** 1/1/2015 1044 **DEM Incident No:**

Responsible Party: QC Energy Resources Texas, LLC

Date Incident: 12/31/2014 **Time Incident:** 1110 **Duration:**

County: Williams **Twp:** 157 **Rng:** 99 **Sec:** 20 **Qtr:** SE SE SW

Lat: 48.40266 **Long:** -103.50580 **Method:** Interpolation from map

Location Description: Bennie Well Site (Hess Bakken Investments II, LLC's SC-BENNIE 157-99-2017H-1, NDIC # 25899)

Directions from Williston, ND: Head East on HWY 2 through Williston, Left on County Rd., 11 past MM-39, Three miles on dirt road to county rd 10, make a left go 1/2 mile to Bennie well site on right hand side

Submitted By: Mack Flinn **Affiliation:** Project Manager/Agent for Carrier

Address: 6001 Cochran Rd.

City: Solon **State:** OH **Zip:** 44139

Received By:

Contact Person: Kathy Cronin
102 Pickering Way Suite 105
Exton, PA 19341

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Discovered spill/unknown cause

Description of Released Contaminant: UN1267 Crude Oil

Volume Spilled: 5.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Unknown. Release was discovered by another driver.

Risk Evaluation:

No immediate health hazards or risks associated.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soils

Action Taken or Planned:

Region 8 Environmental responded on 1/2/2014 out of Williston, ND. They scraped the contaminated soil area and containerized the waste for pending disposal. Waste was staged on-site until sampling results can be obtained to determine whether or not it will be hazardous.

Wastes Disposal Location: Pending disposal facility.

Agencies Involved:

Updates

Date: 1/2/2015 **Status:** Reviewed - Follow-up Required **Author:** Washek, Sandi

Updated Volume: 5.00 gallons

Notes:

Material found off site by company. Company cleanup crew removed the soil and placed on well pad for disposal to proper waste facility as stated in the report. Followup needed.

Date: 1/6/2015 **Status:** Awaiting Documentation **Author:** Martin, Russell

Updated Volume:

Notes:

1/6/2015 at 15:51, on location. Location is at T157 R99 S20, not S6. Wellpad is dual wellpad. Bennie well appears to be Hess's SC-Bennie 157-99-2017H-1. Called report contact to get details on exact location of spill. Received information on cleanup contractor as well as the subcontractor. Left message with subcontractor who performed cleanup. Report contact mentioned impacted material was loaded into a 55-gallon drum. Drum located on site near SC-Bennie tank battery at northwest corner of wellpad and labeled "impacted dirt." Area near barrel on wellpad appears to have been scraped, and there is no visible staining on ground or off location to the west or north. Awaiting confirmation of cleanup location.

Date: 11/5/2015 **Status:** Correspondence **Author:** Martin, Russell

Updated Volume:

Notes:

Email with consultant working with the listed responsible party. Received document verifying cleanup and confirming wellpad is the correct location. Corrected the erroneous location data in the initial spill report on this date. Additionally, consultant showed that the spill occurred on the wellpad, not off, so ultimately NDIC retains jurisdiction of the incident.