

General Environmental Incident Summary

Incident: 3609 **Date/Time Notice:** 1/16/2015 1007 **DEM Incident No:**
Responsible Party: ONEOK Rockies Midstream
Date Incident: 1/16/2015 **Time Incident:** 0900 **Duration:** 1 minutes
County: Williams **Twp:** 155 **Rng:** 103 **Sec:** 21 **Qtr:** SE
Lat: 48.22750 **Long:** -103.94850 **Method:** Navigation quality GPS
Location Description: Stateline Gas Plant
15071 56 th St
Williston, ND 58801
Submitted By: Kim Rudningen **Affiliation:** Env Specialist, ONEOK
Address: 2700 Lincoln Ave SE
City: Sidney **State:** MT **Zip:** 56271

Received By:

Contact Person: Kim Rudningen
2700 Lincoln Ave SE
Sidney, MT 59270

Distance Nearest Occupied Building: 0.25 Miles **Release Contained:** Yes

Type of Incident: Spill

Description of Released Contaminant: water mixed with oil

Volume Spilled: 0.50 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

While the Operator was blowing down the bridle on the reboiler, liquid from the blowdown was being captured in a bucket. However, during transfer of the captured liquid, 1/2 gallon of the water/oil mixture was lost onto the ground below the skid.

Risk Evaluation:

There are no immediate risks associated with this release.

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

This release was contained to a very small area of soil on the facility site. There is no adverse environmental impact to surface or ground water due to this release.

Action Taken or Planned:

The spill will be cleaned up and any contaminated soil will be removed.

Wastes Disposal Location: Soil will be collected and removed to a certified disposal.

Agencies Involved:

Updates

Date: 1/16/2015 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Very small volume of liquid spilled. Cleanup plan is adequate. No on-site inspection necessary.