

# General Environmental Incident Summary

**Incident:** 3689      **Date/Time Notice:** 3/18/2015      15:00      **DEM Incident No:**

**Responsible Party:** Melgaard Construction

**Date Incident:** 3/18/2015      **Time Incident:** 15:00      **Duration:**

**County:** Williams      **Twp:** 158      **Rng:** 95      **Sec:** 25      **Qtr:**

**Lat:** 48.48762      **Long:** -102.90650      **Method:** Interpolation from map

**Location Description:** Gas Gathering Pipeline ROW

**Submitted By:** Jason Henry

**Affiliation:** Hess Corporation

**Address:** 3015 16th Street SW, Suite

**City:** Minot

**State:** ND

**Zip:** 58701

**Received By:**

**Contact Person:**

14058 Jackson Street  
Williston, ND 58801

**Distance Nearest Occupied Building:** 0.4 Miles

**Release Contained:** No

**Type of Incident:** Pipeline Leak

**Description of Released Contaminant:** Condensate and Natural Gas from a gas gathering pipeline release

**Volume Spilled:**

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

**Cause of Incident:**

Excavation contractor struck an 8-inch gas gathering pipeline belonging to Hess Corporation. The excavation contractor was not working for Hess Corporation.

**Risk Evaluation:**

A nearby county road intersection is closed until the damaged gas gathering pipeline can be isolated. The intersection that is closed is 74th Street NW and 103rd Avenue NW in Williams County.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

There was no surface water observed in the immediate vicinity of the release location.

**Action Taken or Planned:**

The damaged pipeline will be isolated and repaired. A nearby county road intersection is closed until the pipeline can be isolated.

**Wastes Disposal Location:**

**Agencies Involved:** Local Emergency Manager, NDIC

## **Updates**

---

**Date:** 3/18/2015    **Status:** Reviewed - Follow-up Required

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

Release from a pipeline leak on a pipeline ROW. Followup is necessary.

---

**Date:** 4/28/2015    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

Arrived on location 14:18 4/28/2015.

No sign of condensate impacts at the location. Excavation filled with water.

No followup is necessary.