

General Environmental Incident Summary

Incident: 3799 **Date/Time Notice:** 7/1/2015 **DEM Incident No:**
Responsible Party: Aggregate Industries
Date Incident: 6/26/2015 **Time Incident:** **Duration:**
County: Cass **Twp:** 136 **Rng:** 51 **Sec:** 21 **Qtr:**
Lat: 46.57508 **Long:** -97.10403 **Method:** Interpolation from map
Location Description: Aggregate Industries - Fargo Cement Terminal, 1702 7th Avenue North,
Fargo, ND.

Submitted By: Patty Christensen **Affiliation:**
Address: 2815 Dodd Road
Suite 101
City: Eagan **State:** MN **Zip:** 55121

Received By:

Contact Person: Patty Christensen
2815 Dodd Road
Suite 101
Eagan, MN 55121

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Tank Collapsed

Description of Released Contaminant: Accelguard 80 (Admixture for use in Ready Mix
Production) - Euclid Chemical

Volume Spilled: **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

The tank which was holding the Accelguard 80 collapsed, resulting in the release of approximately 500 gallons of the product. There was remaining product in the tank which was pumped out by Brett Admixture, who owns the tank. All was product contained on-site using sand which will be appropriately disposed of. No Waters of the State were impacted.

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None. Accelguard 80 is non-hazardous

Action Taken or Planned:

Spill was contained and as much as was possible was absorbed utilizing sand.

Wastes Disposal Location: American Enterprises.

Agencies Involved:

Updates

Date: 7/1/2015 **Status:** Reviewed - No Action Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, approximately 500 gallons of Accelguard 80 (calcium nitrate) was released on-site and contained. Spill was contained and absorbed with sand and will be disposed of at American Enterprises. Material Safety Data Sheet (MSDS) for Accelguard shows only a slight health hazard and no hazard for flammability or reactivity. Since report states that the spill was contained, not near a water body and absorbed using sand, no further follow-up needed at this time.

Date: 7/2/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Received a phone call and email from the Fargo Emergency Manager at 10:30. Email contained photos showing where the tank ruptured and the area after cleanup had taken place. Photos of the area showed no remaining liquid on the ground and the area mostly non-impacted. Only concern in photos is some vegetation along gravel/cement border that is dead and brown in color. Fargo Emergency Manager is in contact with the responsible company's environmental manager and will forward their assessment of the release when completed. Further correspondence needed and photos and email added to folder.

Date: 7/2/2015 **Status:** Awaiting Documentation

Author: O'Gorman, Brian

Updated Volume:

Notes:

Awaiting photos and inspection report from Fargo/Cass Co. Emergency Manager inspection.

Date: 7/2/2015 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Spoke with the Fargo/Cass Co. Emergency Manager at 8:05. He let me know that he will visit the site today, take some photos and make sure no hazards are remaining. No further follow-up unless inspection by Emergency Manager warrants one.