

General Environmental Incident Summary

Incident: 3877 **Date/Time Notice:** 8/25/2015 1045 **DEM Incident No:**
Responsible Party: DGC
Date Incident: 8/25/2015 **Time Incident:** 0700 **Duration:** 15.7 hours
County: Mercer **Twp:** 145 **Rng:** 88 **Sec:** 24 **Qtr:**
Lat: 47.36442 **Long:** -101.82640 **Method:** Interpolation from map
Location Description: DGC
5 mile nw of Beulah, ND of county rd 26
Submitted By: vicente martinez **Affiliation:**
Address: 420 county rd 26
City: beulah **State:** ND **Zip:** 58523

Received By:

Contact Person: vicente martinez
420 county rd 26
beulah, ND 58523

Distance Nearest Occupied Building: 2 Miles **Release Contained:** Yes

Type of Incident: leachate pipe leak

Description of Released Contaminant: ash water

Volume Spilled: 750.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

pvc line had a small slit less than 1 mm thick and two inches wide

Risk Evaluation:

none

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

soil cap area of closed landfill

Action Taken or Planned:

turn off leachate recovery pump off, schedule top of contaminated dirt to be removed and landfilled and replace with clean top soil and seed the cap of landfill

Wastes Disposal Location: sp109

Agencies Involved: Local Emergency Manager

Updates

Date: 8/25/2015 **Status:** Reviewed - Assigned to NDDoH Division

Author: O'Gorman, Brian

Updated Volume:

Notes:

Release, due to a leachate pipe leak, impacted the soil cap area of the closed portion of the landfill. Site permitted through Division of Waste Management which retains oversight.